

COATING PREP

The first step in starting off the project right

This non-residue coating prep product delivers a surface ready for any XL North PTU coatings.

- Very low odor
- Residue-free
- Required use prior to application of PTU coating products
- Coverage: 1:128 to RTU



Pre-Cleaning

Prior to preparing any surface for cleaning and coating

1. Remove all unwanted paint, tape, stickers and adhesive residue prior to cleaning
2. Floor should be swept or vacuumed to remove loose debris and grit

Mixing

1. Add 4 oz. of XL PTU Coating Prep per gallon of room temperature water

Application

XL PTU Coating Prep can be used in automatic scrubbing machines or with a microfiber flat mop and bucket.

Use in Auto scrubber

1. Apply solution down with agitation, leaving vacuum/squeegee off
2. Second pass, turn off solution, leave agitation on and turn on vacuum lower squeegee
3. Use microfiber flat mop to clean up any missed areas
4. Allow to dry completely prior to commencing any coating process

Use with microfiber mop and bucket

1. Apply solution to the surface, damp but not flooding
2. Using the microfiber mop in a singular direction, clean the surface using a figure 8 motion
3. Continue to rinse out mop head (or switch to clean one) so as not to redistribute soil
4. Allow to dry completely prior to commencing any coating process